



**ARUL MURUGAN**  
**DESIGNERS & ASSOCIATES**  
**ENGINEERS & ARCHITECTS**

Lion. **Er.M.V.Mohanraaj** B.E.,M.Tech., M.I.E., F.I.V., M.I.S.T.E.  
Chartered Engineer & Valuer F-9508

**Er. A. Bastin Vasantha Rajan**, B.E.,  
Consulting Civil Engineer

**Ar. M. Vishnu Karthick**, B.Arch.,  
Consulting Architect

**(Dindigul Dist Order No.R.Dis.38851/2002/R4,dt.08-01-2003)**

**REF :** Board of Engineers Proceeding No.BOE/428-6/2002, Dt : 13-11-2002- P.W.D – Chepauk  
– Chennai – Govt. of Tamil Nadu.

**SUB :** SCHOOL – SHRI MAHARISHI VIDYA MANDIR –S.NO:546/2,547/2B,548,549,550/2,551/3 &  
556/1C –SEELAPADI VILLAGE–DINDIGUL PANCHAYAT UNION –DINDIGUL TALUK – DINDIGUL DISTRICT –  
STRUCTURAL STABILITY CERTIFICATE.

I, Er. M.V.MOHAN RAAJ, have been requested by THE CORRESPONDENT – SHRI MAHARISHI VIDYA MANDIR –S.NO:546/2,547/2B,548,549,550/2,551/3 & 556/1C –SEELAPADI VILLAGE–DINDIGUL PANCHAYAT UNION –DINDIGUL TALUK – DINDIGUL DISTRICT to inspect their building school Premises and to issue the necessary Structural stability certificate. The School building was inspected by me on 30.01.2021 and found that the Building is structurally sound based on the present condition and Stability of the building will be safe if proper maintenance is carried out at regular intervals and if the suggestions and Remarks noted in Form-'E' are fulfilled. The Structural Stability Certificate for SHRI MAHARISHI VIDYA MANDIR S.NO:546/2,547/2B,548,549,550/2,551/3 & 556/1C –SEELAPADI VILLAGE–DINDIGUL PANCHAYAT UNION –DINDIGUL TALUK – DINDIGUL DISTRICT issued for the period from 23.03.2021 to 22.03.2024 subject to regular maintenance and based on suggestions mentioned in Form-'E'. The stability certificate is fit for non-earthquake condition.

**NOTE**

1. Any cracks develop in the structure in the said period should be brought to the notice of the panel Engineer
2. The Structural soundness certificate will be revoked at any time if any defect is found during the said period
3. The panel Engineer reserves the right to inspect the School / College at working hours and if found any defects the structural soundness certificate may be revoked without assigning any reasons.


DATE: 01.02.2021

PLACE: DINDIGUL


  
PANEL ENGINEER

& Regd Valuer No. C/1 574/2002-2003 Income - Tax Department, Govt of India

& Life Member No. M 129316 of Institution of Engineers, India

  
PRINCIPAL

SHRI MAHARISHI VIDYA MANDIR Email: raej.ayappa@gmail.com

  
CORRESPONDENT  
SHRI MAHARISHI VIDYA MANDIR  
MAHARISHI GARDENS  
SEELAPADI - 624 005  
DINDIGUL DIST., TN, INDIA.

MAHARISHI GARDENS  
SEELAPADI - 624 005  
DINDIGUL DIST., TN, INDIA.